PHOTO REPORT

Roof repair, before and after (sample report)

1 Main St

Company	Sample Roofing Co.
Prepared by	Sample inspector
Report created	Nov 17, 2026, 3:05 PM (this phone's clock, UTC-05:00)
Photos	3 Before, 3 After; 3 pairs, 5 pages
Before	Nov 10, 2026, 9:09 AM – 9:24 AM (from photo files)
After	Nov 17, 2026, 2:14 PM – 2:47 PM (from photo files)
Pairs	Matched in the order the photos were taken: the first Before photo with the first After photo, and so on.
Signatures	1 signature, on the last page
Clock check	6 photos taken with the Asof camera: 6 within 60 s of server time.
Notes	Sample report. The house, address, names, company and times are invented. Each After photo was taken from the same spot as its Before photo, with the Before photo shown faintly over the camera view.

About the data in this report

Each photo is followed by its data and where it came from: the phone's clock at the moment of capture (compared with a web time server when a connection was available), the phone's GPS, and the address as looked up, picked or typed. Photos imported from the gallery carry the date, time and location written in the file by the device that took them. Photos were resized for this report and not otherwise altered.

Pair 1 of 3

BEFORE



Before 1

Note	Front slope, lowest course: three shingles lifted and curled
Taken	Nov 10, 2026, 9:09:47 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10385, -82.27809 ±3 m · phone location at capture · camera facing SW 210° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_090947.jpg

AFTER



After 1

Note	Lowest course: three shingles replaced and sealed
Taken	Nov 17, 2026, 2:14:08 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10387, -82.27810 ±4 m · phone location at capture · camera facing SW 212° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261117_141408.jpg

Pair 2 of 3

BEFORE



Before 2

Note	Chimney: step flashing loose, counter-flashing sealant cracked
Taken	Nov 10, 2026, 9:13:05 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10391, -82.27801 ±3 m · phone location at capture · camera facing N 15° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_091305.jpg

AFTER



After 2

Note	Chimney: new step flashing and counter-flashing, new sealant
Taken	Nov 17, 2026, 2:31:40 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10393, -82.27802 ±4 m · phone location at capture · camera facing N 17° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261117_143140.jpg

Pair 3 of 3

BEFORE



Before 3

Note	Skylight: flashing seal torn along the right side
Taken	Nov 10, 2026, 9:24:51 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10394, -82.27805 ±3 m · phone location at capture · camera facing NE 33° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_092451.jpg

AFTER



After 3

Note	Skylight: flashing replaced, sealed all around the curb
Taken	Nov 17, 2026, 2:47:22 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10396, -82.27806 ±4 m · phone location at capture · camera facing NE 35° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261117_144722.jpg

Signatures

Signed with a finger on the phone that made this report.



Sample homeowner • Homeowner

Signed Nov 17, 2026, 3:02 PM (UTC-05:00, this phone's clock, within 60 s of the time from asof.day)