PHOTO REPORT

Move-out inspection: move-in vs move-out (sample report)

1 Main St, Apt 2B

Company	Sample Property Rentals
Prepared by	Sample landlord
Report created	Nov 6, 2026, 4:05 PM (this phone's clock, UTC-05:00)
Photos	6 Move-in, 6 Move-out; 6 pairs, 8 pages
Move-in	Nov 7, 2025, 10:12 AM – 10:24 AM (from photo files)
Move-out	Nov 6, 2026, 3:40 PM – 3:51 PM (from photo files)
Pairs	Matched in the order the photos were taken: the first Move-in photo with the first Move-out photo, and so on.
Signatures	2 signatures, on the last page
Clock check	12 photos taken with the Asof camera: 12 within 60 s of server time.
Notes	Sample report. The apartment, address, names and times are invented. Move-in photos taken Nov 7, 2025; move-out photos taken Nov 6, 2026, from the same spots. Already there at move-in: carpet stain by the closet door (pair 2), unchanged at move-out. New at move-out: hole in the wall behind the bedroom door, about 2 in, at handle height (pair 4); one bent blind slat in the living room (pair 5).

About the data in this report

Each photo is followed by its data and where it came from: the phone's clock at the moment of capture (compared with a web time server when a connection was available), the phone's GPS, and the address as looked up, picked or typed. Photos imported from the gallery carry the date, time and location written in the file by the device that took them. Photos were resized for this report and not otherwise altered.

Pair 1 of 6

MOVE-IN



Move-in 1 of 6

Note	Living room from the entry: walls, floor and window, no damage
Taken	Nov 7, 2025, 10:12:14 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10389, -82.27806 ±3 m · phone location at capture · camera facing NE 42° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20251107_101214.jpg

MOVE-OUT



Move-out 1 of 6

Note	Living room from the entry: no change
Taken	Nov 6, 2026, 3:40:08 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10391, -82.27807 ±4 m · phone location at capture · camera facing NE 40° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261106_154008.jpg

Pair 2 of 6

MOVE-IN



Move-in 2 of 6

Note	Bedroom carpet by the closet door: existing stain, about 3 in
Taken	Nov 7, 2025, 10:15:51 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10390, -82.27805 ±4 m · phone location at capture · camera facing NW 302° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20251107_101551.jpg

MOVE-OUT



Move-out 2 of 6

Note	Bedroom carpet by the closet door: same stain, no change; carpet cleaned
Taken	Nov 6, 2026, 3:42:37 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10392, -82.27806 ±5 m · phone location at capture · camera facing NW 300° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261106_154237.jpg

Pair 3 of 6

MOVE-IN



Move-in 3 of 6

Note	Kitchen: counters, sink and range clean, no damage
Taken	Nov 7, 2025, 10:18:02 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10391, -82.27804 ±5 m · phone location at capture · camera facing N 12° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20251107_101802.jpg

MOVE-OUT



Move-out 3 of 6

Note	Kitchen: no change
Taken	Nov 6, 2026, 3:45:12 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10393, -82.27805 ±6 m · phone location at capture · camera facing N 10° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261106_154512.jpg

Pair 4 of 6

MOVE-IN



Move-in 4 of 6

Note	Wall behind the bedroom door, at handle height: no damage
Taken	Nov 7, 2025, 10:20:33 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10392, -82.27806 ±3 m · phone location at capture · camera facing W 282° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20251107_102033.jpg

MOVE-OUT



Move-out 4 of 6

Note	Wall behind the bedroom door: NEW hole about 2 in where the door handle meets the wall; drywall pieces on the floor
Taken	Nov 6, 2026, 3:47:55 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10394, -82.27807 ±4 m · phone location at capture · camera facing W 280° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261106_154755.jpg

Pair 5 of 6

MOVE-IN



Move-in 5 of 6

Note	Living room blinds: all slats straight
Taken	Nov 7, 2025, 10:22:10 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10393, -82.27805 ±4 m · phone location at capture · camera facing NE 42° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20251107_102210.jpg

MOVE-OUT



Move-out 5 of 6

Note	Living room blinds: one slat bent in the middle (NEW)
Taken	Nov 6, 2026, 3:49:41 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10395, -82.27806 ±5 m · phone location at capture · camera facing NE 40° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261106_154941.jpg

Pair 6 of 6

MOVE-IN



Move-in 6 of 6

Note	Bathroom vanity, sink and mirror: no damage
Taken	Nov 7, 2025, 10:24:47 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10394, -82.27804 ±5 m · phone location at capture · camera facing E 92° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20251107_102447.jpg

MOVE-OUT



Move-out 6 of 6

Note	Bathroom vanity, sink and mirror: no change
Taken	Nov 6, 2026, 3:51:20 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10396, -82.27805 ±6 m · phone location at capture · camera facing E 90° (true north, phone compass)
Address	1 Main St, Apt 2B · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261106_155120.jpg

Signatures

Signed with a finger on the phone that made this report.



Sample landlord • Landlord

Signed Nov 6, 2026, 4:01 PM (UTC-05:00, this phone's clock, within 60 s of the time from asof.day)



Sample tenant • Tenant

Signed Nov 6, 2026, 4:02 PM (UTC-05:00, this phone's clock, within 60 s of the time from asof.day)