PHOTO REPORT

Roof inspection (sample report)

1 Main St

Company	Sample Roofing Co.
Prepared by	Sample inspector
Report created	Nov 10, 2026, 10:02 AM (this phone's clock, UTC-05:00)
Photos	7 photos, 7 pages
Photos taken	Nov 10, 2026, 9:04 AM – Nov 10, 2026, 9:40 AM (from photo files)
Signatures	1 signature, on the last page
Clock check	**7 photos taken with the Asof camera: 1 with the phone's clock more than 60 s off server time (marked on each photo); 6 within 60 s of server time.**
Notes	Sample report. The house, address, names, company and times are invented. Photo 5 shows how a report marks a photo taken while the phone's clock was off.

About the data in this report

Each photo is followed by its data and where it came from: the phone's clock at the moment of capture (compared with a web time server when a connection was available), the phone's GPS, and the address as looked up, picked or typed. Photos imported from the gallery carry the date, time and location written in the file by the device that took them. Photos were resized for this report and not otherwise altered.

Photo list

No.	Name	Taken	Address	Note
1	Roof inspection 01	Nov 10, 2026, 9:04 AM	1 Main St	Front elevation from…
2	Roof inspection 02	Nov 10, 2026, 9:09 AM	1 Main St	Front slope, lowest c…
3	Roof inspection 03	Nov 10, 2026, 9:13 AM	1 Main St	Main slope, chimney…
4	Roof inspection 04	Nov 10, 2026, 9:18 AM	1 Main St	Left side: gutter full…
5	Roof inspection 05	Nov 10, 2026, 9:24 AM	1 Main St	Main slope, dome sk…
6	Roof inspection 06	Nov 10, 2026, 9:33 AM	1 Main St	Attic: water stain on…
7	Roof inspection 07	Nov 10, 2026, 9:40 AM	1 Main St	Ridge vent and ridge…



Photo 1 of 7

Note	Front elevation from the street: chimney and dome skylight visible on the main slope
Taken	Nov 10, 2026, 9:04:12 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10372, -82.27831 ±4 m · phone location at capture · camera facing NE 52° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_0901.jpg



Photo 2 of 7

Note	Front slope, lowest course above the gutter: three shingles lifted and curled, granules worn off below them
Taken	Nov 10, 2026, 9:09:47 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10385, -82.27809 ±3 m · phone location at capture · camera facing SW 210° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_0902.jpg



Photo 3 of 7

Note	Main slope, chimney: step flashing loose, counter-flashing sealant cracked along the left side
Taken	Nov 10, 2026, 9:13:05 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10391, -82.27801 ±3 m · phone location at capture · camera facing N 15° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_0903.jpg



Photo 4 of 7

Note	Left side: gutter full of leaves, drip edge separated from the fascia, fascia paint peeling
Taken	Nov 10, 2026, 9:18:30 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10380, -82.27822 ±4 m · phone location at capture · camera facing W 290° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_0904.jpg



Photo 5 of 7

Note	Main slope, dome skylight: flashing seal torn along the right side
Taken	Nov 10, 2026, 9:24:51 AM (UTC-05:00) · this phone's clock at capture
Clock	**Warning: this phone's clock was 3 min 12 s ahead of the time from asof.day. The server's time was about Nov 10, 2026, 9:21 AM.**
Location	28.10394, -82.27805 ±3 m · phone location at capture · camera facing NE 33° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_0905.jpg



Photo 6 of 7

Note	Attic: water stain on the decking next to the skylight shaft, stained wood at the shaft corner
Taken	Nov 10, 2026, 9:33:16 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10389, -82.27806 ±11 m · phone location at capture · camera facing NE 30° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_0906.jpg



Photo 7 of 7

Note	Ridge vent and ridge cap, no visible damage; chimney and skylight on the street-side slope
Taken	Nov 10, 2026, 9:40:02 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10396, -82.27803 ±3 m · phone location at capture · camera facing E 95° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261110_0907.jpg

Signatures

Signed with a finger on the phone that made this report.



Sample homeowner • Homeowner

Signed Nov 10, 2026, 9:58 AM (UTC-05:00, this phone's clock, within 60 s of the time from asof.day)