PHOTO REPORT

Vehicle condition report: pickup and return (sample report)

Silver mid-size sedan · 1 Main St, parking lot

Company	Sample Car Rentals
Prepared by	Sample host
Report created	Nov 14, 2026, 5:52 PM (this phone's clock, UTC-05:00)
Photos	4 Pickup, 4 Return; 4 pairs, 6 pages
Pickup	Nov 12, 2026, 9:10 AM – 9:14 AM (from photo files)
Return	Nov 14, 2026, 5:41 PM – 5:45 PM (from photo files)
Pairs	Matched in the order the photos were taken: the first Pickup photo with the first Return photo, and so on.
Signatures	2 signatures, on the last page
Clock check	8 photos taken with the Asof camera: 8 within 60 s of server time.
Notes	Sample report. The car, place, names and times are invented. Mileage at pickup 42,318 mi, fuel full; at return 42,511 mi, fuel full. New at return: scrape on the rear bumper corner, passenger side, about 6 in (pair 2). No other new damage found on the angles photographed.

About the data in this report

Each photo is followed by its data and where it came from: the phone's clock at the moment of capture (compared with a web time server when a connection was available), the phone's GPS, and the address as looked up, picked or typed. Photos imported from the gallery carry the date, time and location written in the file by the device that took them. Photos were resized for this report and not otherwise altered.

Pair 1 of 4

PICKUP



Pickup 1

Note	Front, driver-side corner: no damage
Taken	Nov 12, 2026, 9:10:14 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10402, -82.27795 ±4 m · phone location at capture · camera facing SE 120° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261112_091014.jpg

RETURN



Return 1

Note	Front, driver-side corner: no new damage, dried rain spots on the hood
Taken	Nov 14, 2026, 5:41:02 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10403, -82.27793 ±5 m · phone location at capture · camera facing SE 123° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261114_174102.jpg

Pair 2 of 4

PICKUP



Pickup 2

Note	Rear, passenger-side corner: bumper without damage
Taken	Nov 12, 2026, 9:11:37 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10398, -82.27788 ±4 m · phone location at capture · camera facing NW 300° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261112_091137.jpg

RETURN



Return 2

Note	Rear, passenger-side corner: NEW scrape on the bumper corner, about 6 in (SC)
Taken	Nov 14, 2026, 5:42:28 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10399, -82.27786 ±5 m · phone location at capture · camera facing NW 303° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261114_174228.jpg

Pair 3 of 4

PICKUP



Pickup 3

Note	Front passenger-side wheel: rim and tire without damage
Taken	Nov 12, 2026, 9:12:50 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10404, -82.27791 ±3 m · phone location at capture · camera facing W 250° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261112_091250.jpg

RETURN



Return 3

Note	Front passenger-side wheel: no new damage, light brake dust
Taken	Nov 14, 2026, 5:43:41 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10405, -82.27789 ±4 m · phone location at capture · camera facing W 253° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261114_174341.jpg

Pair 4 of 4

PICKUP



Pickup 4

Note	Odometer 42,318 mi, fuel full
Taken	Nov 12, 2026, 9:14:05 AM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10401, -82.27793 ±5 m · phone location at capture · camera facing E 90° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261112_091405.jpg

RETURN



Return 4

Note	Odometer 42,511 mi (193 mi driven), fuel full
Taken	Nov 14, 2026, 5:45:10 PM (UTC-05:00) · this phone's clock at capture
Clock	Phone clock within 60 s of the time from asof.day
Location	28.10402, -82.27791 ±6 m · phone location at capture · camera facing E 93° (true north, phone compass)
Address	1 Main St · typed in Asof
Source	Taken with the Asof camera
File	Asof_20261114_174510.jpg

Signatures

Signed with a finger on the phone that made this report.



Sample host • Owner

Signed Nov 14, 2026, 5:50 PM (UTC-05:00, this phone's clock, within 60 s of the time from asof.day)



Sample renter • Renter

Signed Nov 14, 2026, 5:51 PM (UTC-05:00, this phone's clock, within 60 s of the time from asof.day)